


SNÄCKVÄXLAR WORM GEAR UNITS

Effekttabell
Performance

NRV
(n1=2800)

M2 Nm	i	P1 kW	n2 1/min		Fr1 N	Fr2 N	
210	7,5	8,9	373,3	NRV 090	715	2446	67
235	10	7,7	280,0		900	2692	
270	15	6,0	186,7		1034	3081	
260	20	4,4	140,0		1120	3391	
250	25	3,4	112,0		1270	3653	
310	30	3,7	93,3		1270	3882	
275	40	2,6	70,0		1270	4273	
265	50	2,0	56,0		1270	4603	
245	60	1,6	46,7		1270	4891	
225	80	1,2	35,0		1270	5383	
200	100	0,90	28,0		1270	5799	
340	7,5	14,4	373,3	NRV 110	950	3090	67
380	10	12,2	280,0		1194	3401	
425	15	9,3	186,7		1336	3893	
420	20	7,0	140,0		1485	4285	
440	25	5,9	112,0		1700	4616	
480	30	5,7	93,3		1700	4905	
460	40	4,1	70,0		1700	5399	
450	50	3,3	56,0		1700	5816	
430	60	2,7	46,7		1700	6181	
380	80	1,9	35,0		1700	6803	
350	100	1,5	28,0		1700	7328	
520	7,5	22,1	373,3	NRV 130	1190	4042	67
580	10	18,7	280,0		1493	4449	
670	15	14,7	186,7		1725	5092	
660	20	11,0	140,0		1912	5605	
670	25	9,0	112,0		2100	6038	
770	30	9,0	93,3		2100	6416	
730	40	6,5	70,0		2100	7062	
700	50	5,1	56,0		2100	7607	
640	60	4,0	46,7		2100	8084	
590	80	3,0	35,0		2100	8897	
520	100	2,2	28,0		2100	9584	
840	7,5	35,7	373,3	NRV 050	1550	5526	67
890	10	28,4	280,0		1848	6082	
910	15	19,8	186,7		1889	6962	
980	20	16,1	140,0		2289	7663	
890	25	12,0	112,0		2494	8254	
920	30	10,5	93,3		2800	8771	
1200	40	10,6	70,0		2800	9654	
1100	50	8,1	56,0		2800	10400	
990	60	6,2	46,7		2800	11051	
920	80	4,6	35,0		2800	12163	
810	100	3,3	28,0		2800	13103	