


SNÄCKVÄXLAR WORM GEAR UNITS

Effekttabell
Performance

NRV

(n1=900)

M2 Nm	i	P1 kW	n2 1/min		Fr1 N	Fr2 N	
340	7,5	4,8	120,0	NRV 090	1040	3570	67
370	10	4,0	90,0		1270	3929	
420	15	3,1	60,0		1270	4498	
390	20	2,3	45,0		1270	4951	
370	25	1,8	36,0		1270	5333	
460	30	1,9	30,0		1270	5667	
410	40	1,4	22,5		1270	6238	
390	50	1,1	18,0		1270	6719	
350	60	0,86	15,0		1270	7140	
315	80	0,63	11,3		1270	7859	
280	100	0,49	9,0		1270	8180	
565	7,5	8,0	120,0	NRV 110	1390	4511	67
620	10	6,6	90,0		1700	4965	
660	15	4,9	60,0		1700	5684	
630	20	3,6	45,0		1700	6256	
660	25	3,1	36,0		1700	6739	
730	30	3,0	30,0		1700	7161	
690	40	2,2	22,5		1700	7882	
680	50	1,8	18,0		1700	8491	
620	60	1,4	15,0		1700	9023	
540	80	1,0	11,3		1700	9931	
490	100	0,80	9,0		1700	10320	
880	7,5	12,3	120,0	NRV 130	1740	5901	67
960	10	10,3	90,0		2100	6494	
1060	15	7,8	60,0		2100	7434	
1040	20	5,8	45,0		2100	8182	
1050	25	4,8	36,0		2100	8814	
1170	30	4,7	30,0		2100	9366	
1100	40	3,5	22,5		2100	10309	
1050	50	2,7	18,0		2100	11105	
940	60	2,1	15,0		2100	11801	
860	80	1,6	11,3		2100	12989	
780	100	1,2	9,0		2100	13500	
1400	7,5	19,5	120,0	NRV 150	2270	8067	67
1480	10	15,7	90,0		2700	8878	
1450	15	10,5	60,0		2645	10163	
1500	20	8,4	45,0		2800	11186	
1380	25	6,3	36,0		2800	12050	
1400	30	5,4	30,0		2800	12805	
1800	40	5,7	22,5		2800	14094	
1600	50	4,1	18,0		2800	15182	
1440	60	3,2	15,0		2800	16133	
1300	80	2,4	11,3		2800	17757	
1150	100	1,8	9,0		2800	18000	